

RECORDS OF FRIABLE AND NONFRIABLE ACBM
(FORM B)

Inspection Date(s): June 7, 2018

THREE-YEAR REINSPECTION

					CDS CODE 57 10579 0113787	
SCHOOL Cesar Chavez Community School					SCHOOL PHONE NUMBER (530) 668-6700	
ADDRESS	(NUMBER)	(STREET)	(CITY)	(ZIP)		
255 West Beamer Street			Woodland	95776		

-IMPORTANT-

Each building and functional space with friable ACBM or friable assumed ACBM listed on this form requires completion of Form C (PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE ACBM OR FRIABLE ASSUMED ACBM). Indicated location of material on blueprint, diagram or narrative in square or linear feet, and attach a copy. (Sec. 763.93).

LINE	BUILDING NAME & FUNCTIONAL SPACE <small>(Indicate Address if Different From Above)</small>	CHECK ONE			CHECK ONE			
		SUR-			ACBM		ASSUMED ACBM	
		FACING	TSI	MISC	FRIABLE	NON-FRIABLE	FRIABLE	NON-FRIABLE
1.	OFFICE PORTABLE			X				X
2.	RESTROOM PORTABLE			X				X
3.	ART STUDIO PORTABLE			X				X
4.	PORTABLE CLASSROOMS 1-3			X				X
5.	YCCP PORTABLE	X		X				X
6.								
7.								
8.								
9.								
10.								
11.								
12.								
13.								
14.								
15.								
16.								
17.								

Z:\Clients\Yolo County Office of Education\18-4798 Cesar Chavez Community School - YCCP Portable - 3 Year\Sites\Cesar Chavez Community School\Form B.wpd

See attached "Homogeneous Materials Records" for all materials and their locations by building. On Form B all buildings are listed, and a summary of all non-friable and friable material is provided. Friable materials and their locations are listed separately under each building on Form B.

THREE-YEAR REINSPECTION HOMOGENEOUS ACBM RECORDS

Date of Inspection: June 7, 2018

District: Yolo County Office of Education

Inspector: Blake Howes

School: Cesar Chavez Community School

Building: Office Portable

Material Class	Material	Homo. Mat. #	% Asb.	F ² (S)/L.F.(L)	Location	Condition: Code & Comments	Friable Yes/No
M	Carpet Adhesive	1	Assumed Positive	2,000 S	Throughout	(1)	N
M	12" Beige Mottled Vinyl Floor Tile	2	Assumed Positive	50 S	Main entry	(1)	N
M	Tan Speckled Sheet Vinyl Flooring	3	Assumed Positive	160 S	Restrooms (2)	(1)	N
M	Base Cove Adhesive	4	Assumed Positive	200 S	Throughout	(1)	N
M	Drywall	5	Assumed Positive	2,000 S	Throughout	(11) Assumed to exist behind tagboard wall panels	N
n/a	2'x4' Ceiling Panels	6	Non-Suspect	2,000 S	Throughout	(13) Panels are plastic coated fiberglass	n/a

Z:\Clients\Yolo County Office of Education\18-4798 Cesar Chavez Community School - YCCP Portable - 3 Year\Site\Site\ Cesar Chavez Community School\HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 7, 2018

District: Yolo County Office of Education

Inspector: Blake Howes

School: Cesar Chavez Community School

Building: Restroom Portable

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	Blue Speckled Sheet Vinyl Flooring	7	Assumed Positive	480 S	Throughout	(1)	N
M	Drywall	8	Assumed Positive	500 S	Throughout	(11) Assumed to exist behind plastic wall panels	N
M	2'x4' Drywall Hard Lid Ceiling Panels	9	Assumed Positive	480 S	Throughout	(1)	N

Z:\Clients\Yolo County Office of Education\18-4798 Cesar Chavez Community School - YCCP Portable - 3 Year\Site\Site\Cesar Chavez Community School\HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 7, 2018

District: Yolo County Office of Education

Inspector: Blake Howes

School: Cesar Chavez Community School

Building: Art Studio Portable

Material Class	Material	Homo. Mat. #	% Asb.	F ² /L.F.	Location	Condition: Code & Comments	Frivable Yes/No
M	Carpet Adhesive	10	Assumed Positive	480 S	Throughout	(1) Present beneath rubber flooring mats	N
M	Base Cove Adhesive	11	Assumed Positive	30 S	Throughout	(1)	N
M	Drywall	12	Assumed Positive	500 S	Throughout	(11) Assumed to exist behind tagboard wall panels	N
n/a	2'x4' Ceiling Panels	13	Non-Suspect	480 S	Throughout	(13) Panels are plastic coated fiberglass	n/a

Z:\Clients\Yolo County Office of Education\18-4798 Cesar Chavez Community School - YCCP Portable - 3 Year\Site\Site\Cesar Chavez Community School\HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 7, 2018

District: Yolo County Office of Education

Inspector: Blake Howes

School: Cesar Chavez Community School

Building: Portable Classrooms 1-3

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	Carpet Adhesive	14	Assumed Positive	2,880 S	Throughout	(1)	N
M	Base Cove Adhesive	15	Assumed Positive	180 S	Throughout	(1)	N
M	Drywall	16	Assumed Positive	3,000 S	Throughout	(11) Assumed to exist behind tagboard wall panels	N
n/a	2'x4' Ceiling Panels	17	Non-Suspect	2,880 S	Throughout	(13) Panels are plastic coated fiberglass	n/a

Z:\Clients\Yolo County Office of Education\18-4796 Cesar Chavez Community School - YCCP Portable - 3 Year\Sites\Cesar Chavez Community School\HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

**THREE-YEAR REINSPECTION
HOMOGENEOUS ACBM RECORDS**

Date of Inspection: June 7, 2018

District: Yolo County Office of Education

Inspector: Blake Howes

School: Cesar Chavez Community School

Building: YCCP Portable

Material Class	Material	Homo. Mat. #	% Asb.	Ft ² /L.F.	Location	Condition: Code & Comments	Friable Yes/No
M	Carpet Adhesive	18	Assumed Positive	900 S	Throughout	(1)	N
M	Blue/Tan Marbled Sheet Vinyl Flooring	19	Assumed Positive	60 S	Restroom	(1)	N
M	Base Cove Adhesive	20	Assumed Positive	50 S	Throughout	(1)	N
M	Drywall & Joint Compound	21	Assumed Positive	1,200 S	Throughout	(1)	N
S	Drywall Texture	22	Assumed Positive	60 S	Restroom Ceiling	(1)	N
n/a	2'x4' Ceiling Panels	23	Non-Suspect	900 S	Throughout	(13) Panels are plastic coated fiberglass	n/a

Z:\Clients\Yolo County Office of Education\18-4798 Cesar Chavez Community School - YCCP Portable - 3 Year\Sites\Cesar Chavez Community School\HMR.wpd

CONDITION CODE

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (25% or more)
Change in Condition: (4) No (5) Yes (If Yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Miscellaneous: (11) Inaccessible, no inspection data (12) Other (Explain under comments) (13) Non-Asbestos/Not Inspected

CONSULT ORIGINAL AND SUPPLEMENTARY INSPECTION REPORTS FOR MATERIALS WITH TRACE AMOUNTS OF ASBESTOS

West Beamer Street

Office Portable



Portable Classrooms 1-3



Art Studio Portable



Restroom Portable



YCCP Portable



Blake Howes

Yolo County Office of Education
Cesar Chavez Community School
255 West Beamer Street
Woodland, CA 95695

Entek Consulting Group, Inc.
4200 Rocklin Road, Suite 7
Rocklin, CA 95677
Map Not to Scale

AHERA 3 Year Reinspection
Performed by: Blake Howes
June 7, 2018
Project #18-4798